

Health Facility Guidelines

Sample – Assessment Report

No	Room Number	Room Name	Design Code	Comment	Consultant Response
<i>GROUND FLOOR</i>					
<i>Emergency Unit</i>					
001		Isolation Room	HFG17.3.5	There does not appear to be any provision for a negative pressure Isolation Room	
002		Dirty Utility	HFG17.2.2	There does not appear to be a Dirty Utility within the Emergency Unit	
003	52.097	WC/Shower Female	ADA4.13.6	The entry door is not accessible	
004	52.099	Patient WC	ADA4.17.3	The minimum depth of the toilet stall has not been achieved and there do not appear to be any grab bars adjacent to the toilet	
005	52.099	Patient WC	HFG17.3.9	The patient toilet does not appear to be equipped with an emergency call facility	
006	52.103	Acute Treatment Area	HFG17.3.6	The spacing between the beds does not appear to comply with the minimum 2.4m	
007	52.103	Acute Treatment Area	HFG17.2.2	Each treatment area should be at least 9m ² ; this does not appear to have been achieved	
008	52.105	Treatment Area	HFG17.3.5	Not every treatment area appears to have its own dedicated hand wash basin	
009	52.110	Patient WC/Ensuite	HFG17.2.2	The number of Patient WC/Ensuites per treatment bay does not appear to be compliant. Only 2 Patient WC/Ensuites are provided for 10 treatment bays	
0010	52.211	Circulation Area	ADA4.13.6	If this is an accessible route, ensure the entry door has no latch combined with a closer – otherwise this door is not accessible	